

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS
DEL,
1- HAR.V,
2-

Vogl House
State Road 78
Harrington vicinity
Kent County
Delaware

HABS DE-173

Documentation: 18 exterior photos (1982)
4 interior photos (1982)
1 data page (1983)

Jack E. Boucher, Photographer July, 1982

DE-173-1 EAST FRONT FROM SOUTHEAST
DE-173-2 EAST FRONT FROM SOUTHEAST, CLOSER
DE-173-3 EAST FRONT
DE-173-4 EAST FRONT FROM NORTHEAST
DE-173-5 EAST FRONT AND NORTH END
DE-173-6 EAST FRONT, DETAIL OF ENTRANCE
DE-173-7 EAST FRONT, DETAIL OF BALCONY OVER ENTRANCE
DE-173-8 EAST FRONT, DETAIL OF STAIRWAY
DE-173-9 EAST FRONT, DETAIL OF WATER TABLE
DE-173-10 EAST FRONT, DETAIL OF BELT COURSE
DE-173-11 EAST FRONT, DETAIL OF WINDOW
DE-173-12 EAST FRONT, DETAIL OF DOUBLE WINDOW
DE-173-13 WEST SIDE, DETAIL OF LEADED STORM WINDOWS
DE-173-14 SOUTH END, DETAIL OF DORMER
DE-173-15 ENTRANCE HALL, LOOKING SOUTH
DE-173-16 ENTRANCE HALL, DETAIL OF STAIRWAY
DE-173-17 LIVING ROOM, LOOKING NORTH
DE-173-18 SUN PARLOR, SHOWING EMBOSSED CARDBOARD WAINSCOT

DE-173-19 SMOKEHOUSE

DE-173-20 CONCRETE COLUMN AND IRON GATE

DE-173-21 CONCRETE FENCE

DE-173-22 CONCRETE STATUARY

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS
DEL,
1-HAR.V,
2-

ADDENDUM TO:
VOGL HOUSE
State Road 277
Harrington Vicinity
Kent County
Delaware

HABS No. DE-173

DE-173-1 through DE-173-22 were transmitted to the Library of Congress in 1983.

INDEX TO COLOR TRANSPARENCIES

All color xeroxes were made from a duplicate color transparency.

Jack Boucher, Photographer, July 1982

DE-173-23 (CT) EAST FRONT FROM SOUTHEAST